ZF5HP21/28/34 (Gen. 2)

1 Automatic Drive • P.O. Box 440 • Bellows Falls, VT 05101-0440 USA (800) 843-2600 • (802) 463-9722 • F: (802) 463-4059 • www.sonnax.com



ZF6-GEN2-ZIP

This Sonnax kit also is available see www.sonnax.com for details.

(1) 95740-71K



Oversized Lubrication Control Valve Kit

Helps cure:

• Low converter pressure/lube failure

Overheating

Note: Requires tool kit F-95740-TL71 & the VB-FIX reaming fixture.

(2) 95740-05K



Oversized Converter Release Regulator Valve Kit

Helps cure:

- Harsh lockup apply & release
- Excessive TCC slip, RPM & related codes

Note: Requires tool kit F-95740-TL5 & the VB-FIX reaming fixture.

(3) 95740-73K



Oversized Bypass Clutch Control Valve Kit

Helps cure:

- Converter overheat, low TCC release pressure
- Excessive TCC slip/cycling RPM

Note: Requires tool kit F-95740-TL73 & the VB-FIX reaming fixture.

(4) 95740-29K

Pressure Regulator Sleeve

Helps cure:

- Harsh/Erratic line pressure
- Broken parts





Helps cure:

- Delayed/No reverse
- Poor shift quality

Note: Requires tool kit F-95740-TL69 & the VB-FIX reaming fixture.



6) 95740-64K

Oversized Solenoid Pressure Regulator Valve Kit

Helps cure:

- Gear ratio/solenoid codes, wrong gear starts
- Delayed engagements

Note: Requires tool kit F-95740-TL17 the VB-FIX reaming fixture.

Click on Sonnax part numbers to see more information.

E-Shift,

Lower Valve Body

NOTE: To identify between ZF6HP19/26/32 (Gen. 1) and ZF6HP21/28/34 (Gen. 2) valve bodies, refer to ZF identification guide found online at www.sonnax.com.

7) 95740-28K

Clutch A & E Control Set of 2 **Boost Valve Kit** Fits 2 Locations

Helps cure:

- Delayed/Harsh forward engagement
- Flare/Neutral on 5-4 downshift

(8) 95740-66K 95740-72K

M-Shift Only E-Shift Only

Oversized Clutch A & Clutch E Control



Valve Kit Fits Either of 2 Locations



Helps cure: • Flare upshifts/downshift bind-ups

• Pressure control out-of-range codes

Note: 95740-66K requires tool kit F-95740-TL66, 95740-72K requires tool kit F-95740-TL72 & they both require the VB-FIX reaming fixture.

(9) 95740-74K

M-Shift Only

Oversized Shift Valve 3 Kit

Helps cure:



• Burned D1 brake

• Harsh reverse engagement

95740-75K

E-Shift Only

Oversized Position Valve Kit

Helps cure:

• Burnt A, B & E clutches



• Various shift complaints

Note: 95740-74K requires tool kit F-95740-TL74. 95740-75K requires tool kit F-95740-TL75 & they

both require the VB-FIX reaming fixture.

(10) 95740-15K

Valve Body Accumulator Set of 7 Piston & Spring Kit Fits 7 Locations

Helps cure:

- Firm up/downshift and/or engagement
- Erratic EDS solenoid control

(11) 95740-27K 2 Large & 6 Small Plugs

(12) 95740-30K

7 Plugs (Internal)

O-Ringed End Plug Kits

Helps cure:

• Soft/Inconsistent shift feel