
ISTA system version: 4.14.14.17050 **Data version: R4.14.14** **Programming data: 4.14.12**
VIN: WBAUT93549A191107 **Vehicle: 3'E91/Sports Wagon/328i/N52/AUTO/US/LL/2009/03**
Int.lev.works: E89X-09-03-510 **Int.lev.(cur.): E89X-11-09-506** **Int.lev.(tar.): -**
Mileage: 187528 km

| Code | Description | Mileage | Existent | Class |
|--------|--|---------|----------|-------|
| S 0076 | No communication possible with: CD changer/iPod interface | 187528 | yes | |
| 002DC3 | DME: Monitoring, terminal 15 | 187520 | No | |
| 0093D2 | MRS: Telltale lamp for front passenger airbag deactivation | 524280 | No | |
| 009CAB | FRM: One terminal 15 missing | 187520 | No | |
| 009CAC | FRM: Brake-light switch faulty | 187520 | No | |
| 00A0B0 | CAS: Input, brake lights, implausible | 524280 | No | |
| 00A0B1 | CAS: Input, selector-lever position, implausible | 524280 | No | |
| 00A0B5 | CAS: Fault, road speed signal | 524280 | No | |
| 00A118 | CAS: Roadspeed signal implausible | 524280 | No | |
| 00A554 | Instrument cluster: No message (telephone) | 187520 | No | |
| 00C907 | JBE: K-CAN Communication fault | 0 | No | |
| 00C908 | JBE: K-CAN line fault | 0 | No | |
| 00C914 | No message (status, air conditioning, 0x246), receiver JBE, transmitter IHKA/SZL | 187520 | No | |
| 00C91E | No message (terminal status, 0x130), receiver JBE, transmitter CAS | 0 | No | |
| 00CD94 | Message error (ambient temperature / relative time, 0x310), DME receiver, instrument panel transmitter | 187520 | No | |
| 00CDA0 | Message error (terminal status, 0x130), DME receiver, CAS transmitter | 187520 | No | |
| 00CDA8 | Message (status, instrument panel, 0x1B4) faulty, receiver DME, transmitter KOMBI | 187520 | No | |
| 00CDA9 | Message error (air conditioning request, 0x1B5), DME receiver, IHKA transmitter | 187520 | No | |
| 00CF14 | No message (terminal status) from CAS, receiver DKG/EGS, transmitter DME-DDE/CAS | 187520 | No | |
| 00CF1A | No message (status, central locking system) from CAS, receiver DKG/EGS, transmitter CAS/DSC | 187520 | No | |
| 00CF1E | No messages from instrument panel, receiver DKG/EGS, transmitter DSC/KOMBI | 187520 | No | |
| 00D104 | RDC: K-CAN line fault | 187520 | No | |
| 00D107 | RDC: K-CAN communication fault | 187520 | No | |
| 00D358 | Message (KOMBI, 0x784) missing, receiver DSC, transmitter KOMBI | 187520 | No | |
| 00D359 | Message (KOMBI, 0x816) missing, receiver DSC, transmitter KOMBI | 524280 | No | |
| 00D35A | No message (CAS 0x304), receiver DSC, transmitter CAS | 187520 | No | |
| 00D904 | CAS: K-CAN line fault | 187520 | No | |
| 00DA04 | SHD: K-CAN line fault | 524280 | No | |
| 00E0C4 | FLA, K-CAN: line fault | 187520 | No | |

| | | | |
|--------|--|--------|----|
| 00E0C7 | FLA, K-CAN: communication fault | 187520 | No |
| 00E2C4 | CON: K-CAN line fault | 524280 | No |
| 00E2C7 | CON: K-CAN communication fault | 524280 | No |
| 00E2D4 | Message (terminal status, 0x130) faulty, receiver CON, transmitter Car Access System | 524280 | No |
| 00E444 | SMFA: K-CAN line fault | 187520 | No |
| 00E584 | FRM: K-CAN Line fault | 187520 | No |
| 00E587 | FRM: K-CAN communication fault | 187520 | No |
| 00E594 | No message (steering angle), receiver FRM, transmitter SZL/LWS/DSC | 187520 | No |
| 00E596 | No message, receiver footwell module, transmitter high beam assistance | 187520 | No |
| 00E5C4 | CID: K-CAN line fault | 187520 | No |
| 00E5C7 | CID: K-CAN Communication fault | 187520 | No |