



SUBJECT

Interference Noise from the Loudspeakers

MODEL

All

SITUATION

Interference noise from the door loudspeakers can be heard in all audio modes.

CAUSE

Cause 1: The door panel is improperly fitted (torsion, stress, etc.).

Cause 2: The loudspeaker wiring or the loudspeaker itself is damaged.

CORRECTION

Work through the appropriate test modules integrated in ISTA diagnosis.

Cause 1: Test module **W6513_WAS1 Noise from speaker** (refer to Attachment A).

Cause 2: Test module **B6512_AudioCICR-Speaker** (refer to Attachment B).

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty.

Cause1:

Defect Code: 51 41 00 39 00

Labor Operation: **Labor Allowance:** **Description:**

Refer to KSD	Refer to KSD	Door trim panel, front (incl. module carrier, front)
		Unpleasant noise

Defect Code: 51 42 00 39 00

Labor Operation: **Labor Allowance:** **Description:**

Refer to KSD	Refer to KSD	Door trim panel, rear (incl. module carrier, rear)
		Unpleasant noise

Cause2:

Defect Code: 65 12 00 39 00

Labor Operation: **Labor Allowance:** **Description:**

Refer to KSD	Refer to KSD	Speaker (including speaker carrier)
		Unpleasant noise

ATTACHMENTS

view PDF attachment [B653209 Attachment A.](#)

view PDF attachment [B653209 Attachment B.](#)

[Copyright © 2009 BMW of North America, LLC]