



**SUBJECT**

**M57Y FC: 4B1C Fuel Filter Heating, Control**

**MODEL**

E70 and E90 with M57Y

**SITUATION**

During diagnosis, the fault code 4B1C (Fuel filter heating, control) is stored in the DDE.

**CAUSE**

This fault code is generated due to a software error in the diagnostics of the DDE.

**Information**

Do not replace any parts. This fault will not turn on the "Service Engine Soon" lamp. Continue with diagnosis of other faults if they are stored in the DDE. This error in the software will be corrected in a later version of ISTA.

**WARRANTY INFORMATION**

For information only

[ Copyright ©2010 BMW of North America, Inc. ]