

1
2
3
☰

🏠
🔄
🖨️
🔧
?
📄
⌵
✕

ISTA+

📄
⚙️
✉️
✕

VIN **0B91063**
Vehicle **X/E70/off-road vehicle/X5 xDrive35d/M57/AUTO/US/LL/2012/07**
KL 15: --
KL 30: --

DDE 004530 Charging pressure control, high-pressure stage, control deviation: Charging pressure too low/positive control deviation

🖨️
✕

Description
Details

Fault code
4530

Fault text
Charging pressure control, high-pressure stage, control deviation: Charging pressure too low/positive control deviation

Fault types
 Fault currently not present
 Charge-air pressure too low/positive control deviation
 Fault does not trigger a driver information at the moment.

Occurrence [km]: 161248 Occurrence time [s]:

Environment conditions

Condition	First fault memory entry
Frequency	1
Logistics counter	31
Mileage/km reading	161248 km
SAE diagnostic trouble code	P0299
Engine speed	2182.5 1/min
Coolant temperature	25 degC
Rail pressure	486.27 bar
Injection rate	10.59 mg/Hub
Charging pressure	941.18 mbar
Battery voltage	14600 mV
Ambient pressure	804.71 mbar
Engine status	Engine in normal operation
Driving speed	0 km/h
Regeneration status	00420001 hex

Back
Forward
Refresh
Close

