



Facility #7115050
 144 Railroad Street
 Rochester, NY 14609
 (585) 235-3444
 rediimports@gmail.com

INVOICE

BILL TO
 Michael Linsner

INVOICE # 36820
DATE 03/28/2023

VEHICLE / MILEAGE	TRIM / VIN #	NYS INSPECTION
2011 BMW 335D / 101,659	3.0L DSL / WBAPN7C51BA781752	3/23

ACTIVITY	RATE	QTY	AMOUNT
Vehicle Check Over Courtesy 19-Point Vehicle Check Over	0.00	1	0.00T
Washer Fluid Complimentary windshield washer fluid	0.00	1	0.00T
Battery Test Perform battery starting system and charging system test. Charge battery if needed.	0.00	1	0.00T
Customer Concern When driving over bumps/bumpy roads there is a rattle noise coming from the right front side of the vehicle.	0.00	1	0.00T
Diagnosis Technician took vehicle for test drive and verified customer noise. Tech found that the driver front sway bar links is loose and causing the noise concern. Recommend replacement of the loose link and the the Driver side link as well	130.00	0	0.00T
			Subtotal: 0.00
Misc Part Passenger & Driver front sway bar links	52.56	2	105.12T
Labor Installation of the front sway bar links	130.00	1	130.00T
			Subtotal: 235.12

PAID

Unless otherwise specified in writing, all new parts are warranted by the manufacturer for the earlier of 12 months or 12,000 miles. All parts are new unless otherwise specified. This warranty is non-transferable and valid only for the original purchaser. Warranty may be void from the date of service if any other company has serviced the vehicle. No

SUBTOTAL	235.12
TAX	18.81
TOTAL	253.93
PAYMENT	253.93

We appreciate your business!
 Follow, like and review us to keep up on specials and events!
www.rediimports.com | rediimports@gmail.com



Facility #7115050
 144 Railroad Street
 Rochester, NY 14609
 (585) 235-3444
 rediimports@gmail.com

INVOICE

BILL TO
 Michael Linsner

INVOICE # 36701
DATE 03/20/2023

VEHICLE / MILEAGE 2011 BMW 335D/101,556	TRIM / VIN # 3.0T/WBAPN7C51BA781752	NYS INSPECTION 05/23
---	---	--------------------------------

ACTIVITY	RATE	QTY	AMOUNT
Vehicle Check Over Courtesy 19-Point Vehicle Check Over	0.00	1	0.00T
Washer Fluid Complimentary windshield washer fluid	0.00	1	0.00T
Battery Test Perform battery starting system and charging system test. Charge battery if needed.	0.00	1	0.00T
			Subtotal: 0.00
Customer Concern Customer states Noise in Passenger Rear. Noise in passenger Front. Trunk will not open from key fob or interior button press.	0.00	1	0.00T
Diagnosis Technician found Right rear upper shock mount broken. Suggest replacing both replacing both Upper mounts and shocks.	130.00	0.50	65.00T
			Subtotal: 65.00
Shock Left and Right rear shocks	150.00	2	300.00T
Misc Part Shock Bump Stop washer	10.00	2	20.00T
Misc Part Bump stops	28.00	2	56.00T
Shock Mount New Rear Upper Shock Mount	15.00	4	60.00T
Strut Mount New Rear lower shock mount	32.00	2	64.00T

PAID

We appreciate your business!
 Follow, like and review us to keep up on specials and events!
www.rediimports.com | rediimports@gmail.com

ACTIVITY	RATE	QTY	AMOUNT
Labor Install New shock absorbers, Mounts, Washers and Bump Stops. Test drive and confirm repairs.	130.00	3	390.00T
			Subtotal: 890.00
Control Arm New Right Front control arm. Lower rear ward	109.00	1	109.00T
Labor INstall New Control arm Torque to factory spec. Test drive to confirm repairs.	130.00	1	130.00T
			Subtotal: 239.00
Diagnosis Tech states fuse to power rear lights okay at this time. Tech note no power found at reverse lights rear parking lights license plate lights etc. Technician inspected wiring harness and found 6 broken wires.	130.00	0.60	78.00T
Electrical Supplies New electrical supplies	20.00	1	20.00T
Labor Repair of wiring harness. Test for function.	130.00	1.10	143.00T
			Subtotal: 241.00
Alignment Alignment/ Check all tire pressures	150.00	1	150.00T
Alignment Coupon Alignment coupon -\$20.00	-20.00	1	-20.00T
			Subtotal: 130.00

Unless otherwise specified in writing, all new parts are warranted by the manufacturer for the earlier of 12 months or 12,000 miles. All parts are new unless otherwise specified. This warranty is non-transferable and valid only for the original purchaser. Warranty may be void from the date of service if any other company has serviced the vehicle. No warranty of any kind (parts or labor) on any customer-supplied and/or used parts. We are not responsible for damage caused by theft, fire or acts of nature. All personal items should be removed from the vehicle before it is left for service. We are not responsible for these items.

SUBTOTAL	1,565.00
TAX	125.20
TOTAL	1,690.20
PAYMENT	1,690.20
BALANCE DUE	\$0.00

We appreciate your business!
Follow, like and review us to keep up on specials and events!
www.rediimports.com | rediimports@gmail.com



Facility #7115050
 144 Railroad Street
 Rochester, NY 14609
 (585) 235-3444
 rediimports@gmail.com

INVOICE

BILL TO
 Michael Linsner

INVOICE # 28989
DATE 09/28/2021

VEHICLE / MILEAGE 2011 BMW 335d 92,384	TRIM / VIN # 3.0 DSL / WBAPN7C51BA781752	NYS INSPECTION 03/22
--	--	--------------------------------

ACTIVITY	RATE	QTY	AMOUNT
Customer Concern Customer requests quote for front strut replacement.	0.00	1	0.00T
Strut New front strut assembly.	225.00	2	450.00T
Strut Mount New strut mount assembly.	58.00	2	116.00T
Coil Spring New coil spring.	86.00	2	172.00T
Sway Bar Link New front sway bar link	46.00	2	92.00T
Labor Technician installed new front quick strut assembly.	100.00	5.50	550.00T
			Subtotal: 1,380.00
Alignment Alignment/ Check all tire pressures	120.00	1	120.00T
Discount - Miscellaneous Discount	-20.00	1	-20.00T
			Subtotal: 100.00

PAID

Unless otherwise specified in writing, all new parts are warrantied by the manufacturer for the earlier of 12 months or 12,000 miles. All parts are new unless otherwise specified. This warranty is non-transferable and valid only for the original purchaser. Warranty may be void from the date of service if any other company has serviced the vehicle. No warranty of any kind (parts or labor) on any customer-supplied and/or used parts. We are not responsible for damage caused by theft, fire or acts of nature. All personal items should be removed from the vehicle

SUBTOTAL	1,480.00
TAX	118.40
TOTAL	1,598.40
PAYMENT	1,598.40
BALANCE DUE	\$0.00

We appreciate your business!
 Follow, like and review us to keep up on specials and events!
www.rediimports.com | rediimports@gmail.com