

REP-REP-RAE9011M57T2-1128020\_SCR REP-REP-RAE9011M57T2-1128020\_SCR - Replacing  
tensioning device for alternator drive belt (M57T2-SCR) - V.4&comma; VIN: XXXXXXX

ISTA system version	4.05.31.20245	Data version	R4.05.31	Programming data	-
VIN	XXXXXXXX	Vehicle	3/E90/SEDAN/335d/M57/AUTO/US/LL/2010/08		
Int.lev.works	-	Int.lev.(cur.)	-	Int.lev.(tar.)	-
Mileage	0 km				


11 28 020

Replacing tensioning device for  
alternator drive belt (M57T2-SCR)



Necessary preliminary tasks:

- Remove [fan cowl](#).
- Remove [pressure pipe](#) (charge air cooler to EGR valve).
- Remove [alternator](#).



Release screw (1) and remove roller (2).

Release screw (3) and remove tensioning pulley with lever (4) in direction of arrow.

Release screws (1).

Remove belt tensioner in direction of arrow.

*Installation note:*

Replace gasket (2).

