CARLY DIAGNOSTICS REPORT



BMW - E90

2006

Aug 26 2020

STATUS

TOTAL ISSUES

HEALTHY SYSTEMS



Very Bad

8

7

Issues (5)



Fault code: 002A82

This fault results from a generic communication issue in the ECU: Engine / Motor (Internal GR92)

Foot Well Module

Fault code: 009CBC

This fault results from a generic communication issue in the ECU: Fussraummodul /FRM (Internal GR92)

Fault code: 009CC1

This fault results from a generic communication issue in the ECU: Fussraummodul /FRM (Internal GR92)

Fault code: 009CCF

This fault results from a generic communication issue in the ECU: Fussraummodul /FRM (Internal GR92)

🗘 Instrument Cluster

Fault code: 00A554

This fault results from a generic communication issue in the ECU: Instrument cluster / Kombiinstrument (Internal GR92)

Fault code: 00A559

This fault results from a generic communication issue in the ECU: Instrument cluster / Kombiinstrument (Internal GR92)

Junction Box Passenger Module

Fault code: 009C69

This fault results from a generic communication issue in the ECU: Junction Box Passenger / Beifahrer (Internal GR92)

Dynamic Stability Control (DSC)

Fault code: 005DE3

This fault results from a generic communication issue in the ECU: Dynamische Stabilitaets Kontrolle / DSC (Internal GR92)

Healthy Systems (7)	
⊘	Seat Electronics
⊘	Fuel Pump
⊘	Transmission (GS 19)
⊘	Car Access System
⊘	Airbag
⊘	Dynamic Management
⊘	Air Conditioning