

Dealer Operator / General Manager	Sales New Vehicles	Sales Used Vehicles	Business Manager (F&I)	Service	Parts & Accessories	Administration
Date: Bulletin # Replaces	08/06 65 06 06	Source: Name: Title: Phone:	Aftersales Business Development & Marketing Elijah Bernard Accessory Development Manager – Electronics (201) 307-4239			

# Aftersales Business Development & Marketing BMW Dealer Bulletin

## Subject: BMW iPod Interface for MOST Bus Vehicles



### General Information:

Aftersales is excited to announce the iPod interface for MOST Bus vehicles. The device integrates the Apple iPod into the BMW audio system and allows customers to control and listen to their iPod music collection by using the vehicle's iDrive, radio and steering wheel controls, if equipped.

The interface is compatible with the following MOST Bus vehicles: 3 Series (E90, E91, E92), 5 Series (E60, E61), and 6 Series (E63, E64). However, this device cannot be used in conjunction with the 6-disc CD Changer. 7 Series (E65, E66) retrofit coding for PROGMAN is not yet available and will be released later this year.

The installation kit consists of two wiring harnesses and an interface module. The interface module is connected to the MOST Bus, located behind the dash and has a cable running to the glove box of the vehicle. The connector located in the glove box of the vehicle provides the connection between the iPod and the vehicle. It also charges the iPod while connected and the vehicle is running.

Using the CD Changer mode on the iDrive or radio controls, customers can access the functionality of their iPod. CD1 allows the customer to listen to their own customized play lists, CD2 by artist names, CD3 by album title, CD4 by music genre, CD5 by Podcast, and CD6 displays a selection of songs from their music library. Additional features such as Repeat, Random and Scan can also be selected.

## Important:

- The interface module is compatible with 4<sup>th</sup> and 5<sup>th</sup> generation iPods, iPod mini and iPod nano. The interface is not compatible with the 3<sup>rd</sup> generation iPod or earlier and the iPod shuffle.
- This device cannot be used in conjunction with the 6-disc CD Changer.

## Parts Information:

Description	Part Number	MSRP
iPod Interface MOST with Harness	65 11 0 403 650	\$319.95
iPod Interface MOST without Harness	65 11 0 403 651	\$299.95



Suggested installation time for this accessory will vary depending on vehicle model & options

(Please refer to installation instructions on ASAP for suggested install time)

## Compatibility Matrix

Vehicle	Production Range	Part Number
3 Series E90/E91/E92	W/O Navigation 03/05 and later With Navigation 09/05 and later	<b>65 11 0 403 650</b>
5 Series E60/E61	W/O Navigation 03/05 and later With Navigation 09/05 and later	<b>65 11 0 403 651</b>
6 Series E63/E64	09/05 and later	<b>65 11 0 403 650</b> w/o factory installed CD Changer  <b>65 11 0 403 651</b> with factory installed CD Changer (CD changer must be removed)

Best regards,

Alan E. Harris  
Vice President  
Aftersales

Greg Marks  
Manager  
Aftersales Business  
Development & Marketing