

Official

Carly Diagnostics Report

3 Coupe (E92), Build Year 2008

categorized as Middle class was diagnosed with Carly on

Oct 06 2018

Carly found 23 control units.

13 fault codes were detected.



Engine / Motor

Fault Code: 00CD99

Fault Explanation: Message (torque demand EGS, B5)

Fault Code: 00CD9E

Fault Explanation: Message (transmission data 2, 1A2)

Fault Code: 00CD9D

Fault Explanation: Message (transmission data, BA)

Fault Code: 002E7F

Fault Explanation: A and FA-CAN, messages (gear)

Fault Code: 00CDB0

Fault Explanation: Embassy (display transmission data 1D2)



ABS / DSC / Brake

Dynamische Stabilitaets Kontrolle / DSC

Fault Code: 00D357

Fault Explanation: :CAN message / lumbar Error: message LWS1 (ID 0x1F5) missing (RCV) (DSC-ECU received). / CAN fault: Embassy DELAY ANF ACC (ID 0x0AD, (ST DCRN BRP TAR ACC)) is missing! / CAN BUS CAN open F / PT-CAN transmission 1 - Transmission data message 186 missing / PT-CAN: Embassy DELAY ANF ACC (ID 0x0AD) not

received (received by DSC SG). [Channel: ACC]





Advanced Crash and Safety Management (ACSM)

ECU OK, no Fault Code





Transmission Control

Transmission / Getriebe GS 19

Fault Code: 00511B

Fault Explanation: :error coding





Instrument cluster

Instrument cluster / Kombiinstrument	
Fault Code: 00A559	
Fault Explanation: :Klemme30g f shutdown / KL30g f shutdown / KL.30g f shutdown / KL30g f Cutoff	Y
Fault Code: 00A3AA	
Fault Explanation: :CAN ID 1D2 ERROR failure message transmission data / CAN ID 1D2 ERROR message transmission data / CAN ID 1D2 ERROR message Gear data	
Central info display / Zentrales Display	
ECU OK, no Fault Code	



Heating / AC

Air conditioning / Klimaanlage

ECU OK, no Fault Code





Immobilizer System

CAS

ECU OK, no Fault Code





Park distance control

Park Distance Control / PDC

ECU OK, no Fault Code





Roof / Dach

Fault Code: 00A670

Fault Explanation: :BSS error signal line BSS 0xA670 / Error fogging

sensor 0xA670





Audio/Navi/Communication

Phone / Telefon	
ECU OK, no Fault Code	•
Tuner Antenna / Antenne	
ECU OK, no Fault Code	
Car Communication Computer CCC	
Fault Code: 00E18C	_
Fault Explanation: :Device has not decreased the monitoring message or confirmed. (Error Monitoring).	^
MASK	
ECU OK, no Fault Code	
Audio-System	
ECU OK, no Fault Code	



Seats

Seats / Sitze	
ECU OK, no Fault Code	
Seats / Sitze	
ECU OK, no Fault Code	



Systems

Junction Box Passenger / Beifahrer	
ECU OK, no Fault Code	
Fuel pump / Kraftstoffpumpe	
ECU OK, no Fault Code	
Car Communication	
ECU OK, no Fault Code	



Anti-theft alarm system

Interior protection / Innenraumschutz		
ECU OK, no Fault Code		
Theft alarm / Diebstahl Warnanlage		
ECU OK, no Fault Code		



Body

Fussraummodul /FRM

Fault Code: 00A8C1

Fault Explanation: :Reversing light Left defective

Fault Code: 00A8B6

Fault Explanation: :Left brake light is defective, PL3 from 07.14 and

SA5A1: LED daytime running lights broken, PL3 from 07.14 and

SA896: daytime running lights Halogen left defective

