

**Goodyear Auto Service Center
601 N Bumby Ave
Orlando FL 32803**

Work Order: 287298
Technician: 59
Date: 4/28/11 12:37 PM



WBAPH7G54ANM53699

BMW 2009-11 E90 Sport Perf 17" Adj 09/08- (Modified Specification)

Front : Left

Actual	Before	Specified Range
-0.8°	-0.8°	-1.0° -0.1°
6.9°	6.9°	
0.11°	0.07°	0.08° 0.15°
16.5°	16.5°	
16.0°	16.0°	

Front : Right

Actual	Before	Specified Range
-0.8°	-0.8°	-1.0° -0.1°
7.0°	7.0°	
0.13°	0.43°	0.08° 0.15°
14.3°	14.3°	
13.7°	13.7°	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0.1°	0.1°	-0.5° 0.5°
-0.2°	-0.2°	-0.5° 0.5°
2.2°	2.2°	
0.22°	0.51°	0.17° 0.30°

Rear : Left

Actual	Before	Specified Range
-1.4°	-1.2°	-1.8° -1.3°
0.17°	0.18°	0.12° 0.18°

Rear : Right

Actual	Before	Specified Range
-1.8°	-1.9°	-1.8° -1.3°
0.14°	0.31°	0.12° 0.18°

Camber
Toe

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0.2°	0.8°	-0.5° 0.5°
0.31°	0.49°	0.23° 0.37°
0.01°	-0.00°	-0.20° 0.20°